




SAFE WORKING PRACTICE

| JOB/ACTIVITY | ASSOCIATED RISK ASSESSMENTS/SWP's |
|---|--|
| Bundling Stock – Incoming Raw Materials (Gantry Storage Only) SWP/Bundle Requirements | |

| ACTION |
|---|
| <ol style="list-style-type: none">1. Each bundle MUST have a minimum of 5 bands along the length.2. Bands are to be high tensile flat steel strapping e.g. Megadyn 32mm x 0.8mm or equivalent.3. There MUST be no bundles weighing more than 3 tonnes.4. No single bars will be accepted and loads that do not have the above strapping requirements in place will be refused.5. All bundles MUST be positioned so the chances of them 'snatching' are minimised i.e. in-line with NASS guidance (as per the image below) <div style="text-align: center;"></div> |