



SAFE WORKING PRACTICE

JOB/ACTIVITY	ASSOCIATED RISK ASSESSMENTS/SWP's
Bundling Stock – Incoming Raw Materials - Coil SWP/Bundle Requirements	

ACTION
<ol style="list-style-type: none">1. Each coil MUST have a minimum of 3 bands equally spaced around the circumference of the coil.2. Bands MUST pass through the inside diameter of the coil and be fastened on the outside wall of the coil.3. Bands MUST not be over tightened so that they compress the coil excessively4. Bands are to be high tensile flat steel strapping e.g. Megadyn 32mm x 0.8mm or equivalent.5. Maximum coil weight varies depending on the machine the coil is ordered for. <div data-bbox="660 943 1062 1283"></div> <div data-bbox="730 1312 778 1375"></div> <div data-bbox="932 1312 979 1375"></div>